

MKS Pressure Input Module Pin-outs

Signal (J15) Connector

1	
2	Analog In 0-10 VDC
3	
4	
5	Power Common
6	-15 VDC
7	+15 VDC
8	
9	
10	
11	
12	Pressure Output Return
13	
14	
15	Chassis Ground

