

120 Capacitance Manometer Pin-outs

| Pin | Description |
|---------------|------------------------------|
| 1, 25 | Chassis Common |
| 7 | Digital Common |
| 9 | Pressure Output + |
| 10 | Pressure Output Common |
| 11 | Supply Input - |
| 12 | Supply Input + |
| 15 | Remote Zero Input |
| 16 | x 0.1 Range Input |
| 17 | Remote Zero Overrange Output |
| 18 | Range Identification Output |
| 19 | Remote Zero Bypass Input |
| 2-6, 8 | Reserve |
| 13, 14, 20-24 | No Connection |